


# RCC | Remote Charge Cooler


















## C18

## C27 & C32

## 3516C

### ENGINE

	C18	C27 & C32	3516C
RCC UNIT #	 RCC1001	 RCC1001 (2)-UNITS	 RCC1501 (2)-UNITS
FRAME #	 RCC1001FA	 RCC1002FA	 RCC1502FA
RCC & FRAME #	 RCC1001AFA	 RCC1002AFA	 RCC1502AFA
PIPE KIT #	 RCC1001PC1800	 RCC1002PC2732	 RCC1502P3516C
RCC, FA, PK	 RCC1001-C1800	 RCC1002-C2732	 RCC1502-3516C

Due to high temperatures in the units and the connection pipe kits, fully insulating these components to prevent injury is the responsibility of the end user



phone 262-942-1414 fax 262-942-1410 toll free 800-919-9559  
web [www.iearad.com](http://www.iearad.com) email [sales@iearad.com](mailto:sales@iearad.com)

Corporate Headquarters 9625 55th Street, Kenosha, WI 53144